

Fax :

DOL: 08/01/2026
Insured:

Date Taken:
10/20/2026

Description:
photos taken 10/20/26 at tow yard



Date Taken:
10/20/2026

Description:
VIN



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 3.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026




Photo #: 4

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 5.

Date Taken:
10/20/2026

Taken By:

Description:
repair ticket shows him him him mileage at
743,802 on 7/13/26



Photo #: 6

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

EE: 1

Photo #: 7.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026

Photo #: 8

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026

Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 9.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026




Photo #: 10

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 11.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Photo #: 12

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 13.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Photo #: 14

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 15.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026




Photo #: 16

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 17.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026




Photo #: 18

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 19.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Photo #: 20

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026

Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 21.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Photo #: 22

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:




Photo #: 23.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Photo #: 24

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026

Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 25.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026




Photo #: 26

Date Taken:
10/20/2026

Taken By:

Description:
left front wheel damage



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 27.

Date Taken:
10/20/2026

Taken By:

Description:
damaged left fender



Photo #: 28

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 29.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Photo #: 30

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026




Fax :

DOL: 08/01/2026
Insured:

Date Taken:
10/20/2026

Description:
Uploaded on 10/21/2026



Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 33.

Date Taken:
10/20/2026

Taken By:

Description:
left fairing torn off vehicle




Photo #: 34

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 35.

Date Taken:
10/20/2026

Taken By:

Description:
left sleeper damage



Photo #: 36

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 37.

Date Taken:
10/20/2026

Taken By:

Description:
left rear damage




Photo #: 38

Date Taken:
10/20/2026

Taken By:

Description:
left rear damage



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 39.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026




Photo #: 40

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 41.

Date Taken:
10/20/2026

Taken By:

Description:
damage to left rear rear tires





Photo #: 42

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026




Fax :

DOL: 08/01/2026
Insured:


Date Taken:
10/20/2026

Description:
Uploaded on 10/21/2026



Date Taken:
10/20/2026

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 45.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Photo #: 46

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 47.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026




Photo #: 48

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 49.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Photo #: 50

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 51.

Date Taken:
10/20/2026

Taken By:

Description:
right fairing damage




Photo #: 52

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 53.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026

4409



Photo #: 54

Date Taken:
10/20/2026

Taken By:

Description:
damage to right side of sleeper



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 55.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026




Photo #: 56

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 57.

Date Taken:
10/20/2026

Taken By:

Description:
right fender damage



Photo #: 58

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 59.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026




Photo #: 60

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 61.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Photo #: 62

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:

Photo #: 63.

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Photo #: 64

Date Taken:
10/20/2026

Taken By:

Description:
Uploaded on 10/21/2026



Office :

Fax :

Claim #:
Claimant:

DOL: 08/01/2026
Insured:



Photo #: 67.

Date Taken:
10/20/2026

Taken By:



Description:
Uploaded on 10/21/2026