

Heavy Equipment Inspection Report

Company

Company Loss Number

Today's Date

10/23/2026

Insured

Equipment Owner

Date of Loss

Type of Loss

Location of Inspection – Actual Physical Location

10/16/2026

Physical Damage

Year

Make

Model

Type of Equipment

Date of Manufacture

2022

Kubota

SVL65-2

Skid Steer

03/29/2022

Identification Number (PIN)

Hours on Equip.

Engine MFG.

Engine Model / No. Cyls.

1802

Kubota

/ 4

Engine Enclosures

Grill Guard

Vandalism Protect

Sweeps

Forestry Package

Yes

Yes

No

No

No

Rubber Tire Equipment

Front Tire Size

%Worn

Rear Tire Size

%Worn

4 Wheel Drive

Loader Bucket

Backhoe Bucket

L

L

Yes

No

R

R

Fire Extinguisher/Type

Grapple Make

Grapple Size

Dual Arch

Winch

Yes

No

Yes

No

Backhoe

Feller Buncher MFG.

Feller Buncher Size

Feller Buncher Model & S/N

Fixed

Extendable

Crawler Equipment

Width of Track Shoe

No. Track Rollers

S.A.L.T. Tracks

EST% of U/C Worn

Rear Ripper / Type

12" - 23/32

4

Yes

No

Winch / Type / Capacity

ROPS / EROPS Cab Screens

Dozer Blade Type / Style

No

Yes

No

No

Additional Equipment/Attachments/Accessories

Guide Book Value – Quick Sale

Guide Book Value - Resale

Actual Cash Value / Market

Remarks:

Adjuster

Location

Condition of Equipment

Good