

Office :

Fax :

Claim #:
Claimant:

DOL: 10/09/2026
Insured:

Photo #: 1.

Date Taken:
10/29/2026

Taken By:

Description:
Front license plate on insured vehicle.




Photo #: 2

Date Taken:
10/29/2026

Taken By:

Description:
Left rear view.



Office :

Fax :

Claim #:
Claimant:

DOL: 10/09/2026
Insured:




Photo #: 3.

Date Taken:
10/29/2026

Taken By:

Description:
Uploaded on 10/29/2026

Photo #: 4

Date Taken:
10/29/2026

Taken By:

Description:
Right rear view from rear of sleeper.

Office :

Fax :

Claim #:
Claimant:

DOL: 10/09/2026
Insured:

Photo #: 5.

Date Taken:
10/29/2026

Taken By:

Description:
Damaged panel.




Photo #: 6

Date Taken:
10/29/2026

Taken By:

Description:
Right rear view of sleeper, fairing is missing.



Office :

Fax :

Claim #:
Claimant:

DOL: 10/09/2026
Insured:

Photo #: 7.

Date Taken:
10/29/2026

Taken By:

Description:
Rear of sleeper.



Photo #: 8

Date Taken:
10/29/2026

Taken By:

Description:
Damaged extender bracket on the rear of sleeper.



Office :

Fax :

Claim #:
Claimant:

DOL: 10/09/2026
Insured:

Photo #: 9.

Date Taken:
10/29/2026

Taken By:

Description:

View from the left rear of sleeper looking at the cab extender and the damage Hi roof.



Photo #: 10

Date Taken:
10/29/2026

Taken By:

Description:

View from the right front.



Office :

Fax :

Claim #:
Claimant:

DOL: 10/09/2026
Insured:

Photo #: 11.

Date Taken:
10/29/2026

Taken By:

Description:
View from the left front.



Photo #: 12

Date Taken:
10/29/2026

Taken By:

Description:
Vehicle identification sticker.



Office :

Fax :

Claim #:
Claimant:

DOL: 10/09/2026
Insured:

Photo #: 13.

Date Taken:
10/29/2026

Taken By:

Description:
Vehicle identification sticker.



Photo #: 14

Date Taken:
10/29/2026

Taken By:

Description:
Odometer shows 500,638 miles.



Office :

Fax :

Claim #:
Claimant:

DOL: 10/09/2026
Insured:

Photo #: 15.

Date Taken:
10/29/2026

Taken By:

Description:
Odometer.



500,638

Photo #: 16

Date Taken:
10/29/2026

Taken By:

Description:
cab interior.



Office :

Fax :

Claim #:
Claimant:

DOL: 10/09/2026
Insured:

Photo #: 17.

Date Taken:
10/29/2026

Taken By:

Description:
cab interior.

Photo #: 18

Date Taken:
10/29/2026

Taken By:

Description:
Damaged panel, left side.



Office :

Fax :

Claim #:
Claimant:

DOL: 10/09/2026
Insured:

Photo #: 19.

Date Taken:
10/29/2026

Taken By:

Description:

View from the left door looking toward the rear of vehicle.




Photo #: 20

Date Taken:
10/29/2026

Taken By:

Description:

Damaged high roof.

